

Synchronous motors

→ synchronous motor converts electrical energy into mechanical energy.

→ synchronous motor is one type of 3- ϕ AC motor which operates from no load to full load.

→ It is similar in construction to a AC Generator (or) Alternator and it is working on the same principle as 3- ϕ induction motor i.e. Rotating magnetic field (RMF) theory and magnetic locking.

characteristics:-

- It runs at synchronous speed only ($N_s = \frac{120f}{P}$)
- The speed can be changed by changing frequency only
- It is not self starting (Inherently not self starting)
- It can be operated at any power factor i.e. lagging, leading & unity p.f.
- It is a double excited machine
- Rotor needs D.C supply
- Synchronous motors are rated between 150kW and 15MW and runs at speeds ranging from 150 to 1800 rpm

Applications :-

- It is used as a synchronous condenser in power generations and substations (connected in parallel with bus bars to improve power factor).
- It is used for improving power factor.
- It is used in textile mills, mining, cement & rubber factories.
- The constant speed equipment such as fans, blowers, centrifugal pumps & motor generator sets.

Dis-advantages :-

- DC excitation is required.
- variable speeds are not possible.
- Not self starting.
- Hunting problem (magnetic locking)
- They can be started under load condition.
- under overload conditions may lose synchronism.
- Synchronous motor can be operated by different ways by changing their excitation.
- High cost

Why synchronous motor is not self starting?

- It is doubly excited motor. The stator is excited by a 3- ϕ AC supply and the rotor is excited by a D.C. supply.
- The stator produces rotating magnetic field (RMF) and the rotor produces stationary flux.
- The relative speed b/w RMF and rotor flux which is called synchronous speed. At the time of starting it should not be zero.
- The product of these two fluxes is not in phase and not unidirectional.
- In one cycle of operation, the average torque per cycle is zero.
- The rotor is also having inertia. Due to the inertia of the rotor it vibrates at a fixed position instead of rotating.
- So because of all the reasons, we can say that the synchronous motor is not self starting machine.

Principle of operation:-

- When a 3- ϕ winding is fed by a 3- ϕ supply, magnetic flux of constant magnitude but rotating at synchronous speed, is produced.
- Consider a two-pole stator in which are shown two stator poles (N_s and S_s) rotating at synchronous speed, say, in clockwise direction.





fig 1(1)



- With the rotor position as shown, suppose the stator poles are at that instant situated at points A & B . The two similar poles, N (of rotor) & N_s (of stator) as well as S and S_s will repel each other, with the result that the rotor tends to rotate in anti-clockwise direction.

- But half a period later, stator poles, having rotated around, interchange their positions i.e. N_s is at point B & S_s at point A.
- Under these conditions N_s attracts S and S_s attracts N. Hence rotor tends to rotate clockwise (which is just the reverse of the first direction).
- Hence we find that due to continuous and rapid rotation of stator poles, the rotor is subjected to a torque which is rapidly reversing i.e. in quick succession.
- The rotor is subjected to torque which tends to move it first in one direction and then in the opposite direction.
- Owing to its large inertia, the rotor cannot instantaneously respond to such quickly-reversing torque, with the result that it remains stationary.
- From the fig (2) the stator and rotor poles are attracting each other.
- It means that if the rotor poles also shift their positions along with the stator poles, then they will continuously experience a unidirectional torque i.e. clockwise torque as shown in fig.

COMPARISON BETWEEN SYNCHRONOUS MOTOR and INDUCTION MOTOR:

SYNCHRONOUS MOTOR

- 1) construction is complicated
- 2) It is double excited machine.
- 3) It is not self starting
- 4) It is constant speed motor
- 5) The speed is always synchronous speed irrespective of the load.
- 6) speed control is not possible.
- 7) It can be used as synchronous condenser.
- 8) It can be operated at any pf (lagging, leading & UPF)
- 9) Hunting problem is present
- 10) It is costly and maintenance is more.

INDUCTION MOTOR.

- 1) construction is simple particularly in the case of squirrel cage IM
- 2) It is single excited machine.
- 3) It is self starting.
- 4) It is variable speed motor.
- 5) speed is always less than synchronous speed.
- 6) speed control is possible but difficult.
- 7) It cannot be used as a synchronous condenser.
- 8) It can be operated only at lagging pf.
- 9) Hunting problem is not present
- 10) It is cheap and maintenance is less.

Phasor diagram of synchronous motor under

No load:-

i) with out 4/s

$$E_{ph} \longleftarrow \longrightarrow V_{ph}$$

$$|E_b| = |V_{ph}| \Rightarrow I_{th} = 0$$

$$E_b = 4.44 K_p K_d f \phi T \rightarrow (1)$$

$$E_{bph} = V_{ph} - I_a Z_s \rightarrow (2)$$

$$V_{ph} = E_{bph} + I_a Z_s \rightarrow (3)$$

$$I_{aph} = \frac{V_{ph} - E_{bph}}{Z_s} \rightarrow (4)$$

$$Z_s = R_a + jX_s \rightarrow (5)$$


$$Z_s = \sqrt{R_a^2 + X_s^2} \rightarrow (6)$$

$\therefore \theta =$ impedance angle (or) internal p.f. angle


$$\theta = \tan^{-1} \left(\frac{X_s}{R_a} \right) \rightarrow (7)$$

with losses.

i) light load:- load angle (δ) is small



ii) Heavy load:- load angle (δ) is more.



where

ϕ is power factor angle b/w V & I_a


θ is internal power factor angle b/w E_r and I_a

' δ ' is called load angle (or) torque angle

b/w E_b & V (or) power angle (or) Retard angle


Phasor diagram for non-salient pole cylindrical pole, under load condition!

i) Leading P.f




$$\therefore I_{aph} = \frac{E_{rph}}{Z_s}$$

ii) lagging P.f




iii) unity P.f




Phasor diagrams for salient pole

According to two reaction theory (discussed in synchronous generators unit-4). for lagging, leading and unity power factors, the phasor diagrams are as shown below.


1) lagging p.f.



2) leading p.f.




3. U.P.F. -



Power flow Equations of synchronous motor

The Equivalent circuit diagram of synchronous motor is given in below.



- where
- I_a be the Armature current
 - Z_s be Synchronous impedance
 - E_b be the back emf
 - V be supply voltage.

where the emf induced in synchronous motor will lag behind an angle ' δ '

$$\therefore V = E_b + I_a Z_s$$

$$\therefore I_a = \frac{\bar{V} - \bar{E}_b}{Z_s} = \frac{V\angle 0 - E\angle -\delta}{Z_s\angle \theta}$$

$$\therefore I_a = \frac{V}{Z_s} \angle -\theta - \frac{E}{Z_s} \angle -\theta - \delta$$

complex current (or) conj current

$$I_a^* = \frac{V}{Z_s} \angle \theta - \frac{E_b}{Z_s} \angle (\theta + \delta)$$

\therefore complex power input $S = P + jQ = VI_a^*$

$$\therefore S = V \angle 0^\circ \left[\frac{V}{Z_s} \angle \theta - \frac{E_b}{Z_s} \angle (\theta + \delta) \right]$$

$$S = \left[\frac{V^2}{Z_s} \angle \theta - \frac{E_b V}{Z_s} \angle (\theta + \delta) \right]$$

By separating the real and imag values i.e.
The real value with \cos value and imag with \sin value

$$\therefore P + jQ = \left[\frac{V^2}{Z_s} \cos \theta - \frac{E_b V}{Z_s} \cos (\theta + \delta) \right] +$$

$$j \left[\frac{V^2}{Z_s} \sin \theta - \frac{E_b V}{Z_s} \sin (\theta + \delta) \right]$$

from the above Eq. separate real power (P) &
reactive power (Q)

$$\therefore P = \frac{V^2}{Z_s} \cos \theta - \frac{E_b V}{Z_s} \cos (\theta + \delta)$$

$$Q = \frac{V^2}{Z_s} \sin \theta - \frac{E_b V}{Z_s} \sin (\theta + \delta)$$

If R_a is very small then Z_s become X_s

$\therefore Z_s = X_s$ & angle become $\theta = 90^\circ$

$$\tan \theta = \frac{X_s}{R_a} \Rightarrow \tan \theta = \frac{X_s}{0} \Rightarrow \tan \theta = \infty$$

$\theta = \tan^{-1}(\infty) = 90^\circ$

$$\therefore P = \frac{V^2}{X_s} \cos 90^\circ - \frac{E_b V}{X_s} \cos (90 + \delta)$$

$$\therefore P = 0 + \frac{E_b V}{X_s} \sin \delta \quad \left[\because \text{if } R_a = 0 \right]$$

$\theta = 90^\circ$

$$\therefore \boxed{P = \frac{E_b V}{X_s} \sin \delta}$$

similarly

$$Q = \frac{V^2}{X_s} \sin 90^\circ - \frac{E_b V}{X_s} \sin (90 + \delta)$$

$$Q = \frac{V^2}{X_s} - \frac{E_b V}{X_s} \cos \delta$$

$$\therefore \boxed{Q = \frac{V}{X_s} [V - E_b \cos \delta]}$$

condition for maximum Power input

$$P_{in} = \frac{V^2}{Z_s} \cos \theta - \frac{E_b V}{Z_s} \cos(\theta + \delta)$$

for getting max i/p power $\frac{dP_{in}}{d\delta} = 0$

$$\therefore \frac{dP_{in}}{d\delta} = 0 = \frac{d}{d\delta} \left(\frac{V^2}{Z_s} \cos \theta - \frac{E_b V}{Z_s} \cos(\theta + \delta) \right)$$

$$0 = 0 + \frac{E_b V}{Z_s} \sin(\theta + \delta)$$

$$\sin(\theta + \delta) = 0$$

$$\theta + \delta = \sin^{-1}(0) = 180^\circ$$

$$\therefore \theta + \delta = 180$$

$$\boxed{\delta = 180 - \theta}$$

i.e. The condition for max power


$$\therefore P_{in \text{ max}} = \frac{V^2}{Z_s} \cos \theta - \frac{E_b V}{Z_s} \cos(180^\circ) \quad (\because \theta + \delta = 180)$$

$$\therefore \boxed{P_{in \text{ max}} = \frac{V^2}{Z_s} \cos \theta + \frac{E_b V}{Z_s}} \quad (\because \cos 180 = -1)$$

• Mechanical Power developed in synchronous motor

The equivalent circuit of synchronous motor is

given below



from the above equivalent circuit

$$V = E_b + I_a Z_s$$

$$\therefore I_a = \frac{V - E_b}{Z_s} = \frac{V \angle 0 - E_b \angle -\delta}{Z_s \angle 0}$$

$$I_a = \frac{V}{Z_s} \angle 0 - \frac{E_b}{Z_s} \angle -\delta$$

from for finding complex power we will take

conj. current i.e. I_a^*

$$\therefore I_a^* = \frac{V}{Z_s} \angle 0 - \frac{E_b}{Z_s} \angle 0 + \delta$$

\therefore mechanical power developed is given by

$$P_{mech} = \text{Re} [E_b I_a^*]$$

$$\therefore P_{\text{mech}} = \operatorname{Re} \left[\frac{E_b V}{Z_s} \left[\cos \theta - \frac{E_b}{V} \cos(\theta + \delta) \right] \right]$$

$$= \operatorname{Re} \left[\frac{E_b V}{Z_s} \left[\cos \theta - \frac{E_b}{V} \cos(\theta + \delta) \right] \right]$$

$$P_{\text{mech}} = \operatorname{Re} \left[\frac{E_b V}{Z_s} \left[\cos \theta - \frac{E_b}{V} \cos \theta \right] \right]$$

By taking Real term

$$P_{\text{mech}} = \frac{E_b V}{Z_s} \cos(\theta - \delta) - \frac{E_b^2}{Z_s} \cos \theta$$

If $X_s \gg R_a$ then neglecting R_a then

Z_s becomes X_s i.e. $Z_s = X_s$ & $\theta = 90^\circ$

$$\therefore P_{\text{mech}} = \left[\frac{E_b V}{X_s} \cos(90 - \delta) - \frac{E_b^2}{X_s} \cos 90^\circ \right]$$

$$P_{\text{mech}} = \frac{E_b V}{X_s} \sin \delta$$

~~Scanned~~

condition for maximum mechanical power developed

∴ Let us consider a) take

$$P_{\text{mech}} = \frac{E_b V}{Z_s} \cos(\theta - \delta) - \frac{E_b^{\check{V}}}{Z_s} \cos \theta$$

$$\therefore \frac{dP_{\text{mech}}}{d\delta} = 0$$

$$\frac{d}{d\delta} \left[\frac{E_b V}{Z_s} \cos(\theta - \delta) - \frac{E_b^{\check{V}}}{Z_s} \cos \theta \right] = 0$$

$$\therefore \frac{E_b V}{Z_s} \sin(\theta - \delta) - 0 = 0$$

$$\frac{E_b V}{Z_s} \sin(\theta - \delta) = 0$$

$$\sin(\theta - \delta) = \sin 0$$

$$\theta - \delta = 0$$

$\theta = \delta$ → condition for P_{mech} max

$$\therefore P_{\text{mech}} (\text{max}) = \frac{E_b V}{Z_s} \cos(\theta - \theta) - \frac{E_b^{\check{V}}}{Z_s} \cos \theta$$

$$\therefore P_{\text{mech}} (\text{max}) = \frac{E_b V}{Z_s} - \frac{E_b^{\check{V}}}{Z_s} \cos \theta$$

Torque developed in syn. motor

$$\therefore P_{\text{mech}} / \text{ph} = \frac{E_b V_{\text{ph}} \cos(\theta - \delta)}{Z_s} - \frac{E_b^2 \cos \theta}{Z_s} \rightarrow 0$$

for 3- ϕ synchronous motor, mechanical power developed is given by

$$P_{\text{mech}} = 3 \left[\frac{E_b V_{\text{ph}} \cos(\theta - \delta)}{Z_s} - \frac{E_b^2 \cos \theta}{Z_s} \right]$$

$$\therefore T_{\text{Gross}} = \frac{\text{Power}}{\omega}$$

$$\therefore P_{\text{mech}} = \frac{2\pi N T_{\text{Gross}}}{60}$$

$$\therefore T_{\text{Gross}} = \frac{P_{\text{mech}}}{(2\pi N_s / 60)}$$

$$\therefore T_{\text{Gross}} = \frac{3 \left[\frac{E_b V_{\text{ph}} \cos(\theta - \delta)}{Z_s} - \frac{E_b^2 \cos \theta}{Z_s} \right]}{(2\pi N_s / 60)}$$

→ A 3-phase, 400V, 50Hz, 37.3 kW, star-connected synchronous motor has a full-load efficiency of 88%. The synchronous impedance of motor is $(0.2 + j1.6) \Omega$ /phase. If the excitation of the motor is adjusted to give a leading p.f. 0.9, calculate for full-load (i) The induced emf (ii) total mechanical power developed.

Sol

$$\text{supply voltage / ph} \Rightarrow V_{ph} = \frac{V_L}{\sqrt{3}} = \frac{400}{\sqrt{3}} = 230.94 \text{ V}$$

$$\text{Power input (P}_{in}\text{)} = \frac{\text{Output Power (P}_{out}\text{)}}{\text{efficiency } (\eta)}$$

$$\therefore P_{in} = \frac{37.3 \text{ kW}}{0.88} = 42.386 \text{ kW}$$

$$\therefore \text{full-load current, } I = \frac{P_{in}}{\sqrt{3} V_L \cos \phi}$$

$$\therefore I = \frac{42.386 \times 10^3}{\sqrt{3} \times 400 \times 0.9} = 67.98 \text{ A}$$

$$\therefore \text{impedance / ph } Z_s = (0.2 + j1.6)$$

$$Z_s = \sqrt{(0.2)^2 + 1.6^2} = 1.6125 \Omega$$

$$\therefore \text{impedance drop / ph } E_r = I Z_s$$

$$E_r = 67.98 \times 1.6125 = 109.6 \text{ V}$$

$$\therefore \text{Phase angle } \phi = \cos^{-1}(0.9) = 25.84^\circ$$


$$\text{Internal angle } \theta = \tan^{-1}\left(\frac{X_s}{R_a}\right) = \tan^{-1}\left(\frac{1.6}{0.2}\right)$$

$$\therefore \theta = 82.87^\circ$$

$$\therefore \theta + \phi = 82.87^\circ + 25.84^\circ = 108.71^\circ$$

$$\therefore \cos(\theta + \phi) = \cos 108.71^\circ = -0.321$$

From the phasor diagram given below.



Excitation emf per phase.

$$E = \sqrt{V^2 + E_r^2 - 2VE_r \cos(\theta + \phi)}$$

$$E = \sqrt{(230.94)^2 + 109.6^2 - 2 \times 230.94 \times 109.6 \times (-0.321)}$$

$$E = 285.79 \text{ V}$$

(i) Excitation emf (line value) = $\sqrt{3} \times 285.79 = 495 \text{ V}$.

(ii) total copper l/s = $3 \times I^2 R_a = 3 \times (67.98)^2 \times 0.2 = 2,773 \text{ W}$

(iii) Total mechanical power developed

$$P_{\text{mech}} = \text{power i/p} - \text{total c/w/s}$$

$$= 42,386 - 2,773$$

$$\therefore P_{\text{mech}} = 39.613 \text{ kW}$$

→ A 3-phase star-connected non-salient pole synchronous motor connected to a 6.6 kV mains has an armature impedance of $(2.5 + j15) \Omega/\text{ph}$. The excitation of the machine gives a generated emf of 7.0 kV. The iron & friction losses amount to 10 kW. Determine the output of the motor when operating at a load angle of 31° (electrical).

Sol

Supply voltage (line to line) $V_L = 6.6 \text{ kV}$

Excitation emf (line to line) $E = 7.0 \text{ kV}$

Impedance per phase $Z_s = (2.5 + j15) = 15.207 \angle 80.53^\circ$

load angle ' δ ' = 31°

Internal angle $\theta = \tan^{-1} \frac{X_s}{R_a} = \tan^{-1} \left(\frac{15}{2.5} \right) = 80.54^\circ$

∴ mechanical power developed

$$P_{\text{mech}} = \frac{E_b V_L}{Z_s} \cos(\theta - \delta) - \frac{E_b^2}{Z_s} \cos \theta$$

$$\therefore P_{\text{mech}} = \frac{7000 \times 6600}{15.207} \cos(80.54 - 31) - \frac{7000^2}{15.207} \cos 80.54$$

$$\therefore P_{\text{mech}} = 1,971,458.3 - 529,596.6 = 1,441.86 \text{ kW}$$

∴ motor output = mech i/p - iron & friction l/g

$$= 1,441.86 \times 10^3 - 10 \times 10^3$$

$$\therefore \text{motor output} = 1,431.86 \text{ kW}$$

→ A 20 kW, 400 V, 3-phase, star-connected synchronous motor has per phase impedance of $(0.15 + j0.90) \Omega$. Determine the induced emf, torque angle and mechanical power developed for full load at 0.8 p.f. lagging. Assume 92% efficiency of the motor. Draw phasor diagram.

Sol

$$\text{motor i/p} = \frac{m \cdot O/P}{\eta} = \frac{20 \times 10^3}{0.92} = 21.739 \text{ kW}$$

$$\therefore \text{Armature current, } I = \frac{\text{motor i/p}}{\sqrt{3} V_L \cos \phi} = \frac{21,739}{\sqrt{3} \times 400 \times 0.8}$$

$$\therefore I = 39.222 \text{ A}$$

$$\therefore \text{Supply voltage per phase } V_{ph} = \frac{V_L}{\sqrt{3}} = \frac{400}{\sqrt{3}} = 230.94 \text{ V}$$

$$\text{Resultant voltage } E_r = I \times Z_s = 39.222 \times \sqrt{0.15^2 + 0.9^2}$$

$$E_r = 35.787 \text{ V}$$

$$\text{Internal angle } \theta = \tan^{-1} \left(\frac{X_s}{R_a} \right) = \tan^{-1} \left(\frac{0.9}{0.15} \right) = 80.537^\circ$$


$$\text{Induced emf per phase } E_m = \sqrt{V^2 + E_r^2 - 2VE_r \cos(\theta - \phi)}$$

$$E_m = \sqrt{(230.94)^2 + (35.787)^2 - 2 \times 230.94 \times 35.787 \times \cos(80.537 - 36.87)}$$

$$E_{ph} = \sqrt{53,333.3 + 1,2807 - 11,956.6}$$

$$E_{ph} = 206.54 \text{ V}$$

The phasor diagram



line value of induced emf,

$$E_L = \sqrt{3} E_p = \sqrt{3} \times 206.54 = 357.73 \text{ V}$$

$$\therefore \text{mechanical power developed} = P_{out} - 3I_a^2 R_a$$

$$= 21,739 - 3 \times (39.222)^2 \times 0.15 = 21,047 \text{ kW (or)}$$

$$P_{mech} = \text{---}$$

also tan ϕ is done

$$\frac{E_r}{\sin \delta} = \frac{E_p}{\sin(\theta - \phi)}$$

$$\frac{35.787}{\sin \delta} = \frac{206.54}{\sin(80.54^\circ - 36.86^\circ)}$$

$$\therefore \sin \delta = \frac{35.787 \times \sin(43.66^\circ)}{206.54} = 0.11964$$

$$\therefore \text{torque angle } (\delta) = \sin^{-1} 0.11964 = 6.83^\circ$$

→ A 2,000V, 3-phase, 4-pole, Y-connected synchronous motor runs at 1,500rpm. The excitation is constant and corresponds to an open-circuit voltage of 2000V. The resistance is negligible as compared to synchronous reactance of 3Ω per phase. Determine power input, power factor & torque developed for an armature current of 200 A.

Sol $V_{ph} = \frac{2000}{\sqrt{3}} = 1154.7 \text{ V}$


Induced EMF $E_{ph} = \frac{2000}{\sqrt{3}} = 1154.7 \text{ V}$

Input phase current $I = 200 \text{ A}$

Impedance drop / ph $E_r = IZ_s = 200 \times 3 = 600 \text{ V}$

∴ Internal angle, $\theta = 90^\circ$ (∵ resistance negligible)

∴ Assuming armature current lagging behind the supply voltage by an angle ϕ . Shown in fig,



∴ In ΔAOB we have

$$E^2 = V^2 + E_r^2 - 2VE_r \cos(90^\circ - \phi)$$

$$\therefore 1154.7^2 = 1154.7^2 + 600^2 - 2 \times 1154.7 \times 1154.7 \times \frac{\cos(90^\circ - \phi)}{\sin \phi}$$

$$\therefore \sin \phi = \frac{450}{2 \times 1154.7} = 0.1944$$

$$\therefore \phi = \sin^{-1}(0.1944) = 11.2363^\circ \quad (15.05^\circ)$$

(i) P.f = $\cos \phi = \cos(11.2363^\circ) = 0.981$ (lagging)

(ii) Power I/P = $\sqrt{3} V_L I_L \cos \phi = \sqrt{3} \times 2000 \times 200 \times 0.981 = 679.65 \text{ kW}$

(iii) Torque $T = \frac{\text{Power I/P}}{2\pi N_s/60} = \frac{\text{Power I/P} - \text{Copper L/s in armature}}{2\pi N_s/60}$ (∵ copper L/s = $\frac{I^2 R}{1000}$)

$$\therefore T = \frac{679.65 \times 1000 - \frac{200^2 \times 3}{1000}}{2\pi \times 1500/60} = 4326.82 \text{ N-m}$$

16.11 DIFFERENT TORQUES OF A SYNCHRONOUS MOTOR

The torque required to operate the driven machine at every moment between the initial breakaway and the final shutdown is important in determination of the motor characteristics. The various torques associated with synchronous motors are termed starting torque, running torque, pull-in torque, and pull-out torque.

1. Starting Torque. It pertains to the ability of the motor to accelerate the load. The starting torque, sometimes also called the *breakaway torque*, required by the driven machine may be as low as 10%, as in case of centrifugal pumps, and as high as 200 or 250% of full-load torque, as in case of loaded reciprocating two-cylinder compressors.

The synchronous motor has got no self-starting torque, but in modern synchronous motors, almost any reasonable torque can be had by proper design of the damper windings (by changes in the resistance and size of the damper winding).

2. Running Torque. It is the torque developed by the motor under running conditions. It is determined by the output power and speed of the driven machine. The peak output power determines the maximum torque that would be required by the driven machine. The motor must have a breakdown or a maximum running torque greater than this value so as to avoid stalling of the machine.

3. Pull-in Torque. It refers to the ability of the motor to pull-into synchronism when changing from induction to synchronous motor operation.

4. Pull-out Torque. It pertains to the ability of the motor to remain in synchronism under rated load conditions.

The maximum torque which the motor will develop without pulling out of step (or synchronism) is called the *pull-out torque*.

Its value varies from 1.25 to 3.5 times the full-load torque.